G350209
HOPPS/R.

Fault Report

Customer Name: Hopps	Date: 24/7/23
Customer Reference: 350209	Fitter: CRAIGM
Salesperson:	Salesperson called: Yes/No
Blind Type and number: bam roller	
Fault Description: replace bathroom roller Fabric damaged	
Action to correct: replace bathroom roller.	
Problem fixed on site: Yes/No	
Further action required:	