# Order For Service/Repair

| Supplier | C P |
|---|---|
| Order No. | SO11156 |
| Customer Ref. | RQ00286570 |
| Contact Tel. | 01534 768141 |
| Date of Order | 26-01-2021 |
| Date Required | 02-02-2021 |

| Invoice Details | |
|---|---|
| Name | Customer & Local Services |
| Address | Philip Le Feuvre House La Motte Street |
| | St Helier |
| | |
| Postcode | JE4 8PE |
| Phone | 447370 |

| Delivery Details | |
|---|---|
| Name | Customer & Local Services |
| Address | Philip Le Feuvre House, La Motte Street |
| | St Helier |
| | |
| Postcode | JE4 8PE |
| Phone | 447370 |

| Qty | Product Type | Fabric | Description | Location |
|---|---|---|---|---|
| 1 | | | One blind to be refitted | |

| Date | Issue & Action | Arrival Time | Departure Time | Fitter(s) | Hours Spent | Parts Required | Cost £ |
|---|---|---|---|---|---|---|---|
| 8/02/21 | fabric fell off blind Restuck + Re hung | | | AB | 30 mins | | £55 |
| | Control is broken, brought back | | | BR | 30 mins | | £35 agreed by AB 12.02.21 |
| 12/2/21 | NEW CONTROL AND Replace Broken Bottom rail | | | Steve | 15 mins | control Bottom rail | |
| | Refit | | | DR | 15 mins | | |
| | | | | | | Total: | £55.00 |

WC. 17.02.21 MZ