Staff Nam Adrian

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
SO17794	Measurer	Simon Felton Century House Le Canibut St John JE3 4AD simonjvfelton@icloud.com07797 922561 07797 720522	Shutter Repairs - Blackout Blinds Account Manager: Tamara	15-04-2026	11:00 AM

Notes : To advise regarding possible shutter repairs and the option of add blackout blinds behind shutters in lounge

Location	Supplier	Blind Type /Description	Colour	Qty	Width	Drop	Fitting Height	B or R	Controls	Brackets	Surface	Unit Price
Cinema		Duette 25mm		2	1105	1255	ch#	B		Top		
|		32mm	B/O							|		
|		Bedroom RTS		2	1110	1570	#	B		|		
|		|		1	1105	1570	#	B		|		
|		|								|		
Room		|		3	1155	1530		B		|		
Next		|						~~Ext~~ Install		|		£425
Door		|								|		
|		Plus 1 man	2/B		Hour To	check all shutters						
|		|			Adjust	repair / order	slats					
|		|										
|		|										
|		|										

Comments: # 40x40 BATTEN Required Blocks 100mm long

Surface Fixing
C=Concrete
W=Wood
M=Metal
B=Brick
P-Plastic
T=Tile

Order

Quote

Customer Signature
X
I have checked and agree with the above choices

Target Fitting Date