Fault Report

Customer Name: paxton	Date:
Customer Reference: 7186	Fitter: David
Salesperson:	Salesperson called: Yes/No
Blind Type and number: shutters	
Fault Description: All shutters screw cover strips are coming off, the double sided foam isnt strong enough to hold them	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: Needs stronger double sided tape to hold them on	