Staff Name Andrew

Work Diary

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
TS10085	Surveyors	Mrs. Harrison, 18 Somerset Road, Douglas, IM2 5AD, 07624426033, tommyteapot62@gmail.com		07-05-2024	10:00

Notes : measure up bedroom for new curtain tracks and look at curved bay for new track

Room	Qty	Width	FW R B	Drop	R HH	Product Description	Size	Price Code	HW Col	Cont./Fixings	Special Instructions
FRONT	1	500				Supreme glide WITH OVERLAP					NOT READY fix
Lounge	1	260				SETS.					SHORT STUBBY
											SCREWDRIVER.
TV Room	1	400				" " " "					
						(DRILL FIX DIRECT TO WALL	£45-00.			TO REMOVE CURT	
										OLD TRACK & REFIX NEW	
BEDROOM	1	70				SUPREME GLIDE " "					£120-00.
BACK	1	147				" " " "					
						DRILL 2x1	x2 = £60-00				
	1	55				2x1 BAT (CUSTOMERS PAINT REQ)				£3·30	
	1	147				2x1 BAT. (CUSTOMERS PAINT REQ)				£9·72	
										+ TRACKS	