Measuring Sheet.

Staff Name	Order No	Surveyor	Contact Address	Customer Ref	Date	Time
Andy	TS12620	Measurer	Mrs.Stacey, Rao13 Ballahick Way, Park Field Estate, Ballasalla, 482331, stacey.carter@ymail.com Mrs.Stacey, Rao13 Ballahick Way, Park Field Estate, Ballasalla, 482331, stacey.carter@ymail.com	OFF FARACHER RD Recent Mic STACEYS No. 462374	10-10-2025	08:30:00-09:30:0

Notes : Measure for Wood expressions upstairs rooms (Flint downstairs). Look at broken slat on existing blind - can we repair or swap slat?

Room	Qty	Width	FW R B	Drop	R HH	Product Description	Size	Price Code	HW Col	Cont./Fixings	Special Instructions
DIN	2	531	GS	1798		PFIT Van	25		W	LH WAND	18MM BEED
										RH WAND	
BACK											
BED	1	1245	R		2/3		50				TOP DRILL
				1155	8						
						ALL FLAT PELMETS					
BACK R	1	1245	R	1140			"				"
	1	1809	R	1150			"				"
						KIT BLIND Remove 1 Slat that's damage.					£15-00
						& SWAP WITH THE ONE ON THE					BOTTOM RAIL