

# Fault Report

Customer Name: Fetes.	Date: 20/4/22
Customer Reference: L3117	Fitter: Marc
Salesperson: Steven	Salesperson called: <input checked="" type="radio"/> Yes <input type="radio"/> No <del>Not</del>
Blind Type and number:	
Fault Description: : see attached	
Action to correct: Salesmen going back to see what problems are.	
Problem fixed on site: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Further action required: Used 42mm Screws which went through Wood Plate and Pulled Away from Concrete Wall - Replaced Screws with 25mm Back Again Was Surprised which ribbed out with Blugel But On Missing Bottom Bar Button	