

Fault Report

Customer Name: PETRIE	Date: 20/4/22
Customer Reference: 43397	Fitter: DAVID M.
Salesperson: DAVID M.	Salesperson called: <input checked="" type="radio"/> Yes / <input type="radio"/> No
Blind Type and number: INTU-BEAD. #5, #7, #11 AND #13.	
Fault Description: THE SIDE CHANNELS FOR BLINDS ABOVE SHOULD HAVE A LENGTH REF DROP ON ORDER 299mm - GUMS. ALL FOUR WERE RECEIVED AS 207mm - GUMS DROP, AS ADJACENT BLIND ON ORDER.	
Action to correct: SEND TO ASC : CORRECT "SIDE CHANNELS" FOR 4 X WINDOWS AS PER ORIGINAL ORDER, FOR #5, #7, #11 AND #13.	
Problem fixed on site: Yes / <input checked="" type="radio"/> No	
Further action required: ANALYSIS CORRECT PARTS FROM R/SOW.	