

Fault Report

Customer Name: MCMAMON	Date: 26/4/22
Customer Reference:	Fitter: DAVE
Salesperson: STEVEN	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: 4th SLAT FROM LEFT. NOT MOVING WITH OTHER SLATS, HOOK SPINS 360 DEGREE'S	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:	