

15 Orange Cranes

Fault Report

Customer Name: MCMANON	Date: 26/4/22
Customer Reference: 43503.	Fitter: DAVE
Salesperson: STEVEN	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: 4th SLAT FROM LEFT. NOT MOVING WITH OTHER SLATS, HOOK SPINS 360 DEGREES	
Action to correct: collect Headrail + return to Rainbow.	
Problem fixed on site: Yes/No	
Further action required: New H/Rail - FACTORY FAULT	