

Fault Report

Customer Name: SHEILLS	Date: 06/10/23
Customer Reference: 45421	Fitter: AMO
Salesperson: STEVEN	Salesperson called: Yes
Blind Type and number: PERFECT FIT ROLLER	
Fault Description: BLIND BEING RETURNED FOR NEW FRAME FABRIC ALSO PUCKERING CHAIN CHILD SAFETY CLIP AT BOTTOM LOOSE – TRIED TO RE SCREW NOT WORKING	
Action to correct: RE MAKE NEW FRAME	
Problem fixed on site: No	
Further action required: COMING BACK AS PER STEVEN TO GET ABOVE	