

iBums - Vinna  
MA House

CRAIG  
07920714585

- F10 Carpet which relaced colour features requires to be replaced due to edge being notched (on curve) Also to be tacked down. Exposed corner wall between F10/F11 to be filled, sanded and painted (
- F11 Paint marks on 2 carpet tiles - to be removed or replaced.
- F12 Wall above conduit been stripped due to clean, sealant and paint to be applied to affected area.
- F13 -
- F14 Leading edge of door to be touched up and paint residue on glass removed.
- F15 Blinds behind external column do not abut - Option 1) replace 1 no blind to ensure both ends meet per other blinds or 2) relocate all blinds to that they are flush behind the column to mitigate potential glare in gap affecting operators.
- F16 -
- F17 -
- F18 -
- F19 -
- F20 -

New Ven Blinds No 3  
30mm Width

+ 30mm

Prepared by: Mark MacGillivray

+ Fix To Wall  
Velux Switches

EALMOB  
Gray

0705

SAM  
OSL