

Fault Report

Customer Name: Davidson	Date: 19/7/23
Customer Reference: 46036	Fitter: AMO
Salesperson: Marzenci	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: 1. Vertical	
Fault Description: MIS MEASURE. OLD: 1730X 1970 New: 1876X 1970	
Action to correct: re order new ray 2 extra slats.	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Yes.	

