

# Fault Report

Customer Name:	BRIDGE CARPETS
Customer Reference T 9071	Fitter: AGENT
Salesperson AGENT	Salesperson called: /No
Blind Type and number: 1	
Fault Description: VERTICAL SUPPLIED WITH 16 + 12 CARRIERS (28 ) THIS SISZE SHOULD BE 12 + 12 (24) – Agent can not get slats to sit due to the buch at 16 side	
Action to correct:  Remake H/Rail	
Problem fixed on site: /No	