

# Fault Report

Customer Name: SPM Gilt GAS	Date: 10-7-24
Customer Reference: 47487	Fitter: Stuart + Annie
Salesperson: David	Salesperson called: NO.
Blind Type and number: 5.6.7.8 vertical	
Fault Description: 5+8 - card too short 6+7 - Slats too long	
Action to correct: re order 2 Headrail only re order 2x sets of slats	
Problem fixed on site: NO.	
Further action required: yes re order	

# 47487

David Connor  
SPM Oil & Gas

DAVID 7/2/24  
George Sims 21/2

# BERDEEN

## IND COMPANY

ESTABLISHED 1952

Badentay crescent  
Badentay industrial estate  
portlethen  
AB12 1YD

01224 753666 / 017753846451



ROOM	WIDTH	DROP	MATERIAL	CONTROLS	TYPE	FITTING HEIGHT	BRACKETS
SPACES OFF	1700	915	Dim./w/14	RH RH ✓	89 ✓	2000 ✓	TOP WOOD ✓
	1710	920	H/MIL.	" ✓	" ✓	" ✓	" ✓
	1710	925	Charcoal	" ✓	" ✓	" ✓	" ✓
	1706	910		" ✓	" ✓	" ✓	" ✓
RECEPTION	850	2400	Dim/SILVER	LH LH ✓	"	2000 ✓	FACE ✓
	2100	2900	2872	" " ✓	"	2400 ✓	ALUMINIUM ✓
	2100	"	2872	RH RH ✓	"	" ✓	(USE OLD FITTING) ✓
	850	2400		" " ✓	"	2000 ✓	FITTING (ALUM) ✓
Rm #3	2150	2320		" " ✓	"	2350 ✓	TOP DB ✓
" #4	2880	2320		" " ✓	"	" ✓	" ✓
" #5	1920	2320		" " ✓	"	" ✓	" ✓
" #1	2136	2316		" φ ✓	"	2400 ✓	" ✓
" #2	2870	2320		" " ✓	"	" ✓	" ✓
Gen Kitchen	1920	2332		" " ✓	"	" ✓	" ✓
WATER COOL	1900	2300		LH φ ✓	"	" ✓	" ✓
" #2	1920	1647		RH φ ✓	"	2400 ✓	245 ✓
" #1	3750	1648		LH φ ✓	"	" ✓	" ✓
RAIL	2150	3500		LH CR ✓	"	" ✓	" ✓
"	3240	1648		RH OR ✓	"	" ✓	" ✓
OFFSHOOTING	3240	1648		LS φ ✓	"	" ✓	" ✓
AS RM #1	2120	"		RH B ✓	"	" ✓	" ✓
MIRROR	3700	"		RH φ ✓	"	" ✓	" ✓
Rm #3	1920	1648		LH φ ✓	"	" ✓	" ✓
CONFERENCE	2980	2360		LH DL ✓	"	" ✓	" ✓
REMOVE HIGH	2970	2360		RH DL ✓	240	2400 ✓	IN 1400'S CONCRETE TOP ✓

193 X 4 = 772  
579 + U

190 } 1108  
364 } 831 +  
364 }  
190 }  
316 } 174  
408 }  
292 } 130 + VA  
316 }  
408 }  
292 } 582  
292 } 438 VA  
415 } 332  
415 }  
274 }  
364 } 240 + VA  
364 }  
274 }  
415 }  
245 }  
316 }  
316 }  
100 - FENO  
TOP WOOD FITTING

SPECIAL INSTRUCTIONS  
PALETTE DIM:  
CHARCOAL OR ANTIHALLIC

NOTE: CONFERENCE ROOM HAS ESCUATING, VENTS THESE ARE NOT REQUESTED. HOWEVER QUOTE COST OF REMOVAL OF EXISTING BUDS.



TOT NET = 7532  
- 10% = 6779  
- VAT = 5649 + VA

OPS.