



Fault Report

| | |
|---|---|
| Customer Name: SMITH | Date: 18/2/26. |
| Customer Reference: 50654 | Fitter: AMO. |
| Salesperson:  GREG | Salesperson called: Yes/No |
| Order Inputting Error <input type="checkbox"/> | Mismeasure <input type="checkbox"/> |
| Production Error <input type="checkbox"/> | Supplier Error <input type="checkbox"/> |
| Fitting Error <input type="checkbox"/> | |
| Problem fixed on site: Yes/No | |
| Blind Type and number: HAS 5TH LINE BOX OF BRACKETS (50654 SMITH R) = NOTHING IN TUBE WITH 4x PERMETS | |
| Fault Description: CONNECTORS TO ATTACH RUNS ON PERMET.  | |
| Action to correct: | |