

# Fault Report

Customer Name: <i>WALKER</i>	Date: <i>12/03/26</i>
Customer Reference: <i>51545</i>	Fitter: <i>AMO</i>
Salesperson:	Salesperson called: Yes/ <input checked="" type="radio"/> No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input checked="" type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Blind Type and number: <i>ROLLER NO 2</i>	
Fault Description: <i>TOD BIG ORDERED 1431 SHOULD BE 1410</i>	
Action to correct: <i>SENT TO FACTORY TO CUT IT DOWN</i>	

**ABERDEEN  
BLIND COMPANY**

32 Esslemont Avenue  
Aberdeen  
AB25 1SP  
Tel: 01224 637609  
Email: sales@aberdeen-  
blinds.co.uk

51545

CUSTOMER  
ORDER No.

Q

Customer's Name JAMES WALKER  
Address 1 CAIRNVIEW  
BELHEVIE  
Post Code AB23 8SB

Tel. home \_\_\_\_\_  
Tel. work \_\_\_\_\_  
mobile 07564227029  
email JIMWALKER627@GMAIL.COM

DATE  
MEASURED/ORDERED  
12/02/26

CURTAINS	
PLEATED	✓
ROLLERS	✓
ROMANS	
SHUTTERS	
VENETIAN	
VERTICALS	
VISION	
WOODEN	

AM PM (MEASURING TIME)	
MON	
TUE	
WED	
THU	
FRI	

AM PM (FITTING TIME)	
MON	
TUE	
WED	
THU	
FRI	

PCUST	
NET	
PRESS	
RADIO	
MAG.	
VAN	
RECC.	
SHOP	
TV	
YELL P	
OTHER	

**Balance for order payable on arrangement of installation**

Room	Width	Drop	Slat Size	Colour	Control LH or RH	Fitting Height	Any other Instructions	Price
CONSERVATORY	714	1390	Roll	DECORA	RH	2050	RECESS	145
LEFT TO RIGHT	1431*	1390		LEIGHTON	RH		"	242
	1320	1390		TWILIGHT	RH		"	217
	1244	1390			RH		"	217
	1389	1390			RH		"	217
	1243	1390			RH		"	217
	1320	1390			RH	↓	"	217
FRENCH L	520	1860			LH	1970	FABRIC SIZE	146
DOOR R	520	1860			RH	1970	FABRIC SIZE	146
	714	1390	↓	↓	RH	2050	"	145
CONSERVATORY	691	1786		LOWLITE	RH		"	296
ROOF	671	1786		FESTIVAL SAILWE	RH		"	296
LEFT TO RIGHT	674	1786		SHADOW	RH		"	296
	629	1786			RH		"	296
* 1410				ROOFBLIND POLE				36

alum	anthracite	black	brown	champ-gold	chrome	silver	white	recess size	motorised	wood fix	stone fix	brackets top face
------	------------	-------	-------	------------	--------	--------	-------	-------------	-----------	----------	-----------	-------------------

measured by	fitted	CHEQUE	SPREE
		CARD	

SAFETY DEVICES SUPPLIED WITH GOODS MUST BE FITTED WILL RESULT IN THE BLINDS NOT BEING INSTALLED AND PAY THE FULL AMOUNT. I have ordered the above appointment. If payment is not made in full at that time, the goods does not pass to the customer until payment has been received.

ALLOW A SAFETY DEVICE TO BE LIABLE TO ACCEPT DELIVERY when confirming the installation of full settlement is made. Title of the damage occasioned by such removal.

TOTAL PRICE £ 2670  
DEPOSIT £ 1335  
BALANCE £ 1335

To I  
PRICE Cust

*[Large handwritten scribble]*  
£3129