

# Fault Report

Customer Name: <i>KOTB</i>	Date: <i>18/03/26</i>
Customer Reference: <i>S1559</i>	Fitter: <i>STEVEN</i>
Salesperson:	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: <i>An Bends</i>	
Fault Description: <i>4 P/47 VEN Bends - GOT 6 Holes Per Frame = 4 x 6 = 24 BRACKETS IN BAG 12 NO OK</i>	
Action to correct: <i>TEACH FACTORY How to COUNT</i>	

# ABERDEEN BLIND COMPANY

ESTABLISHED 1952

32 Esslemont Avenue  
Aberdeen  
AB25 1SP

Tel: 01224 637609

Email: sales@aberdeen-blinds.co.uk

51559

CUSTOMER ORDER No.



Customer's Name IMAN KOTB  
Address 11 MILLTIMBER GARDENS  
NORTH  
ABDN Post Code AB13 0AR

Tel. home	
Tel. work	
mobile	<u>07728 388 084</u>
email	

DATE MEASURED/ORDERED  
17/02/26

CURTAINS	
PLEATED	
ROLLERS	
ROMANS	
SHUTTERS	
VENETIAN	
VERTICALS	
VISION	
WOODEN	

AM PM (MEASURING TIME)			PCUST
MON			
TUE			PRESS
WED			RADIO
THU			MAG.
FRI			VAN
AM PM (FITTING TIME)			RECC.
MON			
TUE			TV
WED			YELL P
THU			OTHER
FRI			

## Balance for order payable on arrangement of installation

Room	Width	Drop	Slat Size	Colour	Control LH or RH	Fitting Height	Any other Instructions	Price
<del>FRENCH DOOR</del>				<del>PERFECT FIT</del>				
SIDE SCREEN L	<u>494</u>	<u>1922</u>	<u>25mm</u>	<u>0150 A.</u>	<u>LH</u>	<u>1985</u>		<u>265</u> ✓
DOOR L	<u>654</u>	<u>1770</u>		<u>20MM BRACKETS</u>	<u>LH</u>	<u>1985</u>		<u>273</u> ✓
DOOR R	<u>653</u>	<u>1770</u>			<u>RH</u>	<u>1985</u>		<u>273</u> ✓
SIDE SCREEN R	<u>494</u>	<u>1921</u>			<u>RH</u>	<u>1985</u>		<u>265</u> ✓
WINDOW								
L TOP	<u>389</u>	<u>264</u>						<u>142</u>
L BTM	<u>388</u>	<u>445</u>						<u>167</u>
MID TOP	<u>524</u>	<u>310</u>						<u>167</u>
MID BTM	<u>523</u>	<u>490</u>						<u>167</u>
R TOP	<u>389</u>	<u>265</u>						<u>142</u>
R BTM	<u>387</u>	<u>445</u>		<u>WHITE FRAME</u>				<u>167</u>
				<u>TENSIONED</u>				
							<u>-157</u>	<u>2028</u>

alum	anthracite	black	brown	champ-gold	chrome	silver	white	recess size	motorised	wood fix	stone fix	brackets top	brackets face
							✓						

<u>07941473169</u> measured by	fitted by	date	CASH	CHEQUE	SPREE
<u>BILL CLARK</u>			INVOICE	CARD	

SAFETY DEVICES SUPPLIED WITH GOODS MUST BE FITTED BY US AT THE TIME OF INSTALLATION. REFUSAL TO ALLOW A SAFETY DEVICE TO BE FITTED WILL RESULT IN THE BLINDS NOT BEING INSTALLED. UNDER THE TERMS OF THIS CONTRACT, YOU WILL BE LIABLE TO ACCEPT DELIVERY AND PAY THE FULL AMOUNT. I have ordered the above goods and agree to pay a 50% deposit and the remaining balance when confirming the installation appointment. If payment is not made in full at that time, Aberdeen Blinds have the right to refuse to install the products until full settlement is made. Title of the goods does not pass to the customer until payment has been made in full. Declaring that there shall be no liability for normal damage occasioned by such removal.

TOTAL PRICE £ 1724 1076  
DEPOSIT £ 862 538  
BALANCE £ 862

To Be Confirmed  
PRICE ACCEPTANCE  
Customer's Signature

Special Instructions 2017 ✓ GO AHEAD BILL CLARK  
CALL COST 4 DEP