

# Fault Report

Customer Name MURRAY	Date: 17/03/26
Customer Reference: 51584	Fitter MICHAEL
Salesperson: BILL	Salesperson called: Yes/No
Fault Description: Bedroom rail too short	
Action to correct: Remake rail @ 1278 recess send additional slats	
Problem fixed on site: Yes <input checked="" type="radio"/> No	
Further action required: Yes remake & return to fit.	

# ABERDEEN BLIND COMPANY

ESTABLISHED 1952

32 Esslemont Avenue  
Aberdeen  
AB25 1SP

Tel: 01224 637609

Email: sales@aberdeen-blinds.co.uk

51584

CUSTOMER ORDER No.

Customer's Name MURIEL MURRAY  
Address 24 JAMESFIELD MANOR  
ARCHINGELL ROAD  
ABDN Post Code AB10 7FS

Tel. home	
Tel. work	
mobile	<u>07999206963</u>
email	

DATE MEASURED/ORDERED
<u>24/02/06</u>

CURTAINS	
PLEATED	
ROLLERS	
ROMANS	
SHUTTERS	
VENETIAN	
VERTICALS	<input checked="" type="checkbox"/>
VISION	
WOODEN	

AM PM (MEASURING TIME)		P/CUST
MON		NET
TUE		PRESS
WED		RADIO
THU		MAG.
FRI		VAN
AM PM (FITTING TIME)		RECC.
MON		SHOP
TUE		TV
WED		YELL P
THU		OTHER
FRI		

## Balance for order payable on arrangement of installation

Room	Width	Drop	Slat Size	Colour	Control LH or RH	Fitting Height	Any other Instructions	Price
<u>Bedroom</u>	<u>1173</u>	<u>1153</u>	<u>89mm</u>	<u>SPRASH PLACIDA</u>	<u>RH</u>	<u>2080</u>	<u>SPLIT DRAW</u>	<u>170</u>
<u>Kitchen</u>	<u>1275</u>	<u>1159</u>			<u>RH</u>	<u>2080</u>	<u>SPLIT DRAW</u>	<u>191</u>
<u>LOUNGE</u>								
<u>LEFT</u>	<u>510</u>	<u>1304</u>			<u>RH</u>	<u>2050</u>	<u>LH BUNCH</u>	<u>135</u>
<u>MIDDLE</u>	<u>1960</u>	<u>1302</u>			<u>LH</u>	<u>2050</u>	<u>SPLIT DRAW</u>	<u>198</u>
<u>RIGHT</u>	<u>510</u>	<u>1304</u>	<u>↓</u>		<u>LH</u>	<u>2050</u>	<u>RH BUNCH</u>	<u>133</u>
<u>ALL WAND DRAW</u>								

alum	anthracite	black	brown	champ-gold	chrome	silver	white	recess size	motorised	wood fix	stone fix	brackets top	face
							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	

measured by	fitted by	date	CASH	CHEQUE	SPREE
<u>Bill Cook</u>			INVOICE	CARD	

SAFETY DEVICES SUPPLIED WITH GOODS MUST BE FITTED BY US AT THE TIME OF INSTALLATION. REFUSAL TO ALLOW A SAFETY DEVICE TO BE FITTED WILL RESULT IN THE BLINDS NOT BEING INSTALLED. UNDER THE TERMS OF THIS CONTRACT, YOU WILL BE LIABLE TO ACCEPT DELIVERY AND PAY THE FULL AMOUNT. I have ordered the above goods and agree to pay a 50% deposit and the remaining balance when confirming the installation appointment. If payment is not made in full at that time, Aberdeen Blinds have the right to refuse to install the products until full settlement is made. Title of the goods does not pass to the customer until payment has been made in full. Declaring that there shall be no liability for normal damage occasioned by such removal.

TOTAL PRICE £ 825.00  
DEPOSIT £ 413.00  
BALANCE £ 412.00

To Be Confirmed

PRICE ACCEPTANCE  
Customer's Signature

X. [Signature]

Special Instructions  
1278

PAID STRIKE