

Ordered
G 351530 Headley

Fault Report

Customer Name: Mrs Headley	Date: 2/12/21
Customer Reference: G351530	Fitter: adam
Salesperson: dave	Salesperson called: Yes/No
Blind Type and number: Expression wood blind	
Fault Description: Blind is too wide of the tiles. First measurement was taking from the top of the resces without the tiels being conciderd	
Action to correct: Order new blind 860by1000	
Problem fixed on site: Yes/No	
Further action required:	