

S 351529

McGlynn

# Fault Report

Customer Name: McGlynn	Date: 3/12/21
Customer Reference: 351529	Fitter: CRAN M
Salesperson: Adam	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: roller	
Fault Description: measured wrong	
Action to correct: reinstall roller at 1608mm width	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: replace roller	