

Fault Report

Customer Name: MARKS	Date: 02/12/21
Customer Reference:	Fitter: ADAM
Salesperson:	Salesperson called: Yes/No
Blind Type and number: Roller x 2	
Fault Description: Dog chewed bottom of blinds	
Action to correct: to trim and refit bar	
Problem fixed on site: Yes/No	
Further action required: customer paid £80 service charge	