

S 351399 Wilson. / R

Customer Name: Wilson	Date: 7/12/21
Customer Reference: S 351399	Fitter: Adam
Salesperson: Craig M	Salesperson called: Yes/No
Blind Type and number: Expression wood	
Fault Description: Blind doesn't hit the window ceil. On the specile insrtsions it says the blind will hit the handles. Customer thought it was going to under and she could slide the handels though the slats. The handels match up the the slats and she will be abele to have the blind on the windowcail and the handels though them	
Action to correct: New blind to have a drop of 1410	
Problem fixed on site: Yes/No	
Further action required:	