

*Absoulte
Mess!!*

G 351542
Lee R.

Fault Report

Customer Name: lee	Date: 16/12/21
Customer Reference:	Fitter: CRAMM
Salesperson: adam	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: FT bed room cut down to 1622 width bath cut down to 738 width. S/room short on drop remade 1780 plait should be white Kit roller should have eyelets.	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: cut down rollers and replace wood.	

Collected by Neil 17/12/21