

G 348506

GOW / R1

Fault Report

Customer Name

GOW

Date

19/1/22

Customer Reference

G. 348506 / R.

By

CRAIG M

Salesperson.

Responsibility: Yes/No

Blind Type and number

PLATE

Fault Description:

CUT OUT ON PLATE IN WRONG PLACE.
REMAKE SIDE WITHOUT CUT OUT
AND SEND HANDLE PACKERS

(NO NEED FOR CUT OUT)

Action to correct:

REMAKE PLATE SIDE + HANDLE PACKERS.

Problem fixed on site. Yes/No

Further action required.