


S 351686

# Fault Report

Customer Name: Wilkinson	Date: 24/5/22
Customer Reference: 351686	Filter: CRAM m
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTER.	
Fault Description: replace door panel on kit right door wharped  Right middle door	
Action to correct: Replace right middle door panel (wharped)	
Problem fixed on site: Yes/No	
Further action required:	