

9352092

Fault Report

Customer Name: Loxham	Date: 25/5/22
Customer Reference: 352092	Filter: CRMG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTER	
Fault Description: Need 2 x frame magnets for SHUTTER NO ① LH front bed room as missing and panels popping open.	
Action to correct: 2 x frame magnets.	
Problem fixed on site: Yes/No	
Further action required:	