

G 351520
Wear / R2

Fault Report

Customer Name: Nancy Wear
Date: 21/1/22
Customer Reference: 351520
Error: CRAM in
Salesperson: [blank]
Responsibility: Yes/No

Blind Type and number

Fault Description

remate roller no 3 (too short) should be 124-2 mm
also need 4x brass continuous
chains at 1120 mm

Action to correct: NO 3
remate roller ↑ at 124-2 mm
also 4x chains at 1120 mm.

Problem fixed on site: Yes/No
Further action required