

S 352047
Stevenson/R

Fault Report

Customer Name: Stevenson	Date: 07.02.22
Customer Reference: 352047	Fitter: Scott Johnson
Salesperson: Shawn Hanley	Salesperson called: <input checked="" type="radio"/> Yes <input type="radio"/> No
Blind Type and number: Wood Expressions, Blind 1 & 3 (Livingroom Bay)	
Fault Description: Customer had many complaints. indentations on slats to both small bay blinds.	
Action to correct: N/A	
Problem fixed on site: Yes <input checked="" type="radio"/> No <input type="radio"/>	
Further action required: New blinds need ordered OR new slats to replace damaged and a competent fitter to replace them.	