

G 352146

Young IR

Fault Report

Customer Name: Young	Date: 17.03.22
Customer Reference: 352146	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Blind Type and number: Wood expression, 2, 3, 4, 5, 6, 7, 8, 9, 20	
Fault Description: Blind 2 (DINER BAY) Pelmet needs LH return, Blinds 3, 4, 5 (DINER BAY 2, 3, 4) Dont lie correct (see photo) Blinds 6 (DINER BAY 5) incorrect drop sent to site. Blinds 7, 8, 9 (lounge 1, 2, 3) Dont lie correct (see photos) Blind 20 (Bathroom) incorrect control sizes (see photos)	
Action to correct: N/A part payment took £1381 of £1592 £211 to pay	
Problem fixed on site: Yes/No	
Further action required: New Blinds need ordered for Blinds 6 (DINER BAY 5) and 20 (Bathroom) New pelmet needs ordered for Blind 2 (DINER BAY 2) New blinds may need ordered for Blinds 3, 4, 5, 7, 8, 9 once photos are observed.	