

G 352159
Nichol / R.

Fault Report

Customer Name: Nichol	Date: 08.03.22
Customer Reference: 352159	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: <input checked="" type="radio"/> Yes / <input type="radio"/> No
Blind Type and number: Vertical, Blind 1 (lounge)	
Fault Description: Mismeasure, press	
Action to correct: N/A	
Problem fixed on site: Yes / <input checked="" type="radio"/> No	
Further action required: New headrail needs ordered, new Extra Slates/Vanes needs ordered headrail size 2700mm exact size Slates/Vanes 10nr needed (please check this is correct, we have 26nr)	

10 x Slats
1 x new h/r.