

G 349739

Robertson / R.

Fault Report

Customer Name: Robertson

Date: 2/2/22

Customer Reference: 349739

Filter: CRAIG M

Salesperson:

Salesperson called: Yes/No

Blind Type and number:

Fault Description:

roller no ② made wrong should be 1520mm
But made at 725mm

NOT PAID

Action to correct:

remake roller

Problem fixed on site: Yes/No

Further action required: