

S 351977
Yorston / R

Fault Report

Customer Name: Yorston	Date: 11.3.22
Customer Reference: 351977	Fitter: CRAIG M
Salesperson: Shawn	Salesperson called: Yes/No
Blind Type and number: Curve Track	
Fault Description: Curve TRACK made or ordered wrong (re-order) vanes left on site with customer.	
Action to correct: replace wrong TRACK.	
Problem fixed on site: Yes/No	
Further action required: 21/03/22 - service call SS. customer having new blinds made and keeping these up until new ones fitted.	

Customer Hard Work