


S 351325

Naylor, R

Fault Report

Customer Name: Naylor	Date: 22/2/22
Customer Reference: 351325	Fitter: CRAIG M
Salesperson: CRAIG M	Salesperson called: Yes/No
Blind Type and number: P/PE	
Fault Description: Replace bottom frame from blind no ① (has small mark)  410 x 960	
Action to correct: replace bottom frame (small mark)	
Problem fixed on site: Yes/No	
Further action required:	