

S 350639  
Newby R

# Fault Report

Customer Name: Newby	Date: 27.04.22
Customer Reference: 350639	Fitter: Scott Johnson
Salesperson: Shawn Hanley	Salesperson called: Yes (No)
Blind Type and number: Blind 1 (Lr) curved Vertical	
Fault Description: I have installed the Blind incorrectly, it is into plastic cladding and if it is moved the screw holes will be visible. Customer obviously not happy.	
Action to correct: need to discuss this with Nicole	
Problem fixed on site: Yes (No)	
Further action required: ?	

\* Customer requires a quote to replace cladding \*