

G 352059
Upton/R

Fault Report

Customer Name: Upton	Date: 14.03.22
Customer Reference: 352059	Fitter: Scott Johnson
Salesperson: DAVE	Salesperson called: Yes/ <input checked="" type="radio"/> No
Blind Type and number: Verticals Blind 8 (RH Front Bed), 11 (LH Rear Bed)	
Fault Description: Vanes send incorrect size (Drop)	
Action to correct: Sizes needed Drop: 1155mm (Blind 8) width: 1715mm Drop: 1155mm (Blind 11) width: 1140mm	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Order new Vanes, sizes above	

New Slats Required.