


G 352200
Urrin/R.

Fault Report

Customer Name: Urrin	Date: 1st 3/22
Customer Reference: 352200	Fitter: Craig M
Salesperson:	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: replace bottom frame on plate No ① (scratched)  (870 x 425)	
Action to correct: replace bottom frame.	
Problem fixed on site: Yes/No	
Further action required:	