

G 348046  
Howling R.

# Fault Report

Customer Name: Howling	Date: 24.03.22
Customer Reference: 348046	Fitter: Scott Johnson
Salesperson: PD	Salesperson called: Yes (No)
Blind Type and number: Blind 1 (B/W) Vertical	
Fault Description: Making a grinding noises when tilting the vanes.	
Action to correct: Josh advised to replace headrail and return old one to Factory for further investigations	
Problem fixed on site: Yes (No)	
Further action required: order headrail. Collect old headrail	
New h/r ordered.	