

C 352470

# Fault Report

Customer Name: Fox	Date: 8/12/22
Customer Reference: 352470	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTER NO ①	
Fault Description: replace shutter no ① measured wrong SHUTTER width needs to be 575mm	
Action to correct: replace shutter no ① new sizes 575 x 1803	
Problem fixed on site: Yes/No	
Further action required:	