

S 340856

Oliver / R.

# Fault Report

Customer Name: oliver	Date: 11/4/22
Customer Reference: 340856	Fitter: CRAIG in
Salesperson:	Salesperson called: Yes/No
Blind Type and number: roman	
Fault Description: replace or repair roman as plastic clip inside headrail is snapped and is making chords get wrapped up around inside bar	
Action to correct: Replace or repair.	
Problem fixed on site: Yes/No	
Further action required: Waiting on Craig letting us know what roman.	