

G 352148.
Bullion Lane

Fault Report

Customer Name: Bullion Lane	Date: 19.04.22
Customer Reference: 352146	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: <input checked="" type="radio"/> Yes / <input type="radio"/> No
Blind Type and number: Blind 6 (Nursery) Roller	
Fault Description: Measured incorrect @ 1655mm	
Action to correct: new measurement taken Recess size 2655mm	
Problem fixed on site: Yes <input checked="" type="radio"/> / <input type="radio"/> No	
Further action required: New roller needs ordered	