

S 351974

HMP Low Newton

Fault Report

Customer Name: Hmp/Yol Low Newton	Date: 20.04.22
Customer Reference: 351974	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: Yes <input checked="" type="radio"/> No
Blind Type and number: all blinds	
Fault Description: Guide and wire missing components, I'll send a image of the missing components	
Action to correct: N/A	
Problem fixed on site: Yes <input checked="" type="radio"/> No	
Further action required: parts need ordered.	
Factory Error	