

G 352559  
Hamson/R

# Fault Report

Customer Name: Harrison	Date: 18.11.22
Customer Reference: 352559	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Vertical, front bedroom	
Fault Description: Headrail seams faulty see attached video.	
Action to correct: Tried silicone spray video was taken after spray.	
Problem fixed on site: No	
Further action required: Order new headrail.	