

GAhead



34 HIGH STREET,  
SPENNYMOOR,  
DURHAM DL16 6DB

TEL: 01388 813267 or 0191 258 5956

sales@baileys-blinds.co.uk  
www.baileys-blinds.co.uk

Customer's Name **MAUGHAN**

Address **HIGH BELL RIDGE  
INGOE**

Post Code **NE200SX**

Tel home  
Tel work  
mobile **07710 740850**  
email

DATE MEASURED/ORDERED

**22/7/21**

Measured By:

**DAVE**

CURTAINS  
PLEATED  
ROLLERS **X6**  
ROMANS  
SHUTTERS  
VENETIAN **X3**  
VERTICALS  
VISION  
WOODEN

SPECIAL INSTRUCTIONS

**Bed Blinds in Security  
70 Allow for 5 Blinds**  
**Bed colour to  
confirm if goods  
AHEAD.**  
**CHILD DEVICES +  
ALL CAPS EXPLODED**

348995

PCUST  
NET  
PRESS  
RADIO  
MAG.  
VAN  
RECC  
SHOP  
TV  
YELL P  
OTHER

Fitted By DATE DAY AM PM

rail type & colour  
alum white brown  
white chain  
welded in weight  
recess size  
motorised  
wood fix  
stone fix  
brackets top face

Room	Width	Drop	Slat Size	Colour	Control LH or RH	Fitting Height	Price
<b>THE CATHEDRALS</b> 1260 ①	840	2010	WINDSON	FLOR SHADE	R	2200	162.00
②	1905	2690			L	2400	333.00
<b>MAIN ROOM</b> ①	1880	1950	25	ROSS (6)	R	2100	238.00
②	1880	1950			R		238.00
③	1900	1950			R		238.00
<b>TELEPHONE</b> HALL	1685	1170	MEMPHIS	TAUPE	L	2200	140.00
MID BED	1685	1170			L		140.00
RW BED	1685	1170			L		140.00
KITCHEN	1680	1145		ASH	L	2400	140.00

TOTAL £ **1761.00**

ALL ROLLERS TO BE CUSTOMER'S CHAIN + NO SILENCERS

2% DISC GIVEN - £ **36.00**

\* Service call 03/05/22 - see fault report SJ.

SAFETY DEVICES SUPPLIED WITH GOODS MUST BE FITTED BY US AT THE TIME OF INSTALLATION. IF YOU REFUSE TO ALLOW A SAFETY DEVICE TO BE FITTED, THEN THE GOODS WILL NOT BE INSTALLED, AND UNDER THESE CIRCUMSTANCES YOU WILL STILL BE LIABLE TO PAY THE FULL PRICE UNDER YOUR CONTRACT. YOU ARE STILL BOUND TO ACCEPT DELIVERY OF THE GOODS AND TO PAY FOR BOTH THE FITTING AND INSTALLATION EVEN ALTHOUGH INSTALLATION HAS NOT BEEN CARRIED OUT.

**FIT COMPLETED**

I have ordered the above goods and agree to pay the amount shown in full at the time of fitting. If payment is not made in full at that time Baileys has the right to remove the goods until full settlement is made. Title of the goods does not pass to the customer until payment has been made in full. Declaring that there shall be no liability for normal damage occasioned by such removal.

TOTAL PRICE £ **1400.00**  
DEPOSIT £ **700.00**  
BALANCE £ **700.00**

PRICE ACCEPTANCE Customer's Signature  
**22/7/21 TAKEN AT RAINBOW**

CASH CHEQUE CARD

**ALL BLINDS TO BE PAID FOR AT TIME OF FITTING**



# VEGETIAN BLINDS

## Rainbow Blinds

### Order Form

Rainbow Blinds & Interiors

61 Canyon Road

Excelsior Park

Wishaw

M12 0EG

01698 351 888

F. 01698 351 999

sales@rainbow-blinds.com

T.

Date: 23.7.21

Retailer: BALENS

Address: Gosforth

Order Required:

Telephone:

Email:

Signature:

Purchase Reference No: 318095 (MIRYAN)

Special instructions

W	Slat Width				Width (mm)	Drop (mm)	Recess or Exact	Child Safety Installation Height (mm)	Length of Control (mm)	Slat Range and Colour	OPERATION				ORDER	
	18mm (v)	25mm (v)	35mm (v)	50mm (v)							STD (v)	REV (v)	RHS (v)	LHS (v)	Price (£)	Qty
1	✓				1880	1950	R	2100	✓	7055 (B)						
2	✓				1880	1950	R	2100	✓	7055 (B)						
3		✓			1900	1950	R	2100	✓	7055 (B)						
4																
5																
6																
7																
8																

**NOTES:**

UNLESS OTHERWISE STATED ALL MEASUREMENTS WILL BE TAKEN AS NOTICES

All blinds supplied by Rainbow Blinds & Interiors are fitted with an approved Child Safety Device

Customer Name (Please Print):

The client certifies that the blinds are to be used in accordance with the instructions supplied to operating them.

Customer Signature:

Issue June 2016

Rainbow Blinds - 61 Canyon Road, Excelsior Park, Wishaw, M12 0EG T: 01698 351 888 - F: 01698 351 999 - E: sales@rainbow-blinds.com

348995

# Fault Report

Customer Name: Maughan	Date: 03.05.22
Customer Reference: 348995	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Blind Type and number: Blind 1 (Bed 1 <sup>the</sup> garry) Roller	
Fault Description: Blind is fraying down both sides, see images on email. Brackets have been moved and fitted too tight, customer says they fell and he refitted them.	
Action to correct: new blind needs ordered Width Bracket to Bracket is 820mm.	
Problem fixed on site: Yes/No	
Further action required: order blind.	

\* See new order 13/05/22 -

cloth reselection

