

G350686.

Fault Report

Customer Name: Mathie	Date: 24.05.22
Customer Reference: 350686	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: Yes/No
Blind Type and number: Blind 1 (front Bed) Roller	
Fault Description: indentation in fabric off bottom the bar, advised it will fall out. Customer is going to wait and see if it does. the roller is still sagging causing the fabric to ripple, not as bad as the original.	
Action to correct: N/A	
Problem fixed on site: Yes/No	
Further action required: note on system in case customer calls at a later date.	