

S 350696
Patterson IR

Fault Report

Customer Name: Patterson	Date: 10.05.22
Customer Reference: 350696	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: Yes (No)
Blind Type and number: Blind 1+2 (Patro + Liv) Vertical	
Fault Description: incorrect controls, should be wand control as stated on order.	
Action to correct: customer rebooked for the 19 th May (Afternoon).	
Problem fixed on site: Yes (No)	
Further action required: change to wand control.	

Office Error