

G 352591

Fault Report

| | |
|--|---|
| Customer Name: Sheppard | Date: 30/5/22 |
| Customer Reference: 352591 | Fitter: Scott Johnson |
| Salesperson: Dave | Salesperson called: <input checked="" type="radio"/> Yes / No |
| Blind Type and number: Blind 2 (TopHall @) Roller | |
| Fault Description: Measured incorrectly, (width) | |
| Action to correct: Correct size is 1520mm | |
| Problem fixed on site: Yes <input checked="" type="radio"/> No | |
| Further action required: Blind at unit for Collection. | |