

S 350969
Pearson, R.

Fault Report

Customer Name: Pearson	Date: 05.07.22
Customer Reference: 340884	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: Yes
Blind Type and number: Vision Blind	
Fault Description: Fabric moving on head rail, needs silicone spray to stop squeaking.	
Action to correct: Blind is in the unit for collection.	
Problem fixed on site: No	
Further action required: Seek out problem and solve it.	