

# Fault Report

Customer Name: HMP Holme House	Date: 07/06/22
Customer Reference: 350701	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called <input checked="" type="radio"/> Yes <input type="radio"/> No
Blind Type and number: Vertical X5	Blind 11 (Visitor Room L to R)
Fault Description: Measured incorrect,	
Action to correct: headrail needs to be 20mm shorter x 5 (RR headrails) these have been handed over to Neil (driver) on Tuesday 07th June.	
Problem fixed on site: Yes <input checked="" type="radio"/> No <input type="radio"/>	
Further action required: <del>REPAIR</del> REPAIR HEADRAILS. CUT DOWN HEADRAILS & SEND BACK TO S'MOOR	