

Fault Report

Customer Name: Brown	Date: 10.08.22
Customer Reference: 352832	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: All Blinds verticals	
Fault Description: Dinner-head rail too wide should be 1755mm Bay- Drop should be 1325mm on both sets of vanes All vanes should be 5 inch.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: All blinds need reordered.	
<u>Refunded</u>	